

Inspection Photos
Location Name: MOSSBERG J-65N66W /30SESE
Location #: 310537



Photo #1

Mossberg J 30-23 (05-123-26554) Wellsite

Temporarily Abandoned | TA

Emergency contact number remains NOT accurate

from prior FIR



Photo #2

Mossberg J 30-23 Wellsite

Temporarily Abandoned | TA

Emergency contact number NOW accurate

Inspection Photos

Location Name: MOSSBERG J-65N66W /30SESE

Location #: 310537



Photo #3

Mossberg J 30-23 Battery site

Abandoned

*All Equipment has been removed
from prior FIR*

