

Inspection Photos
Location Name: GRAY B 19X
Location ID: 05-103-66397
Inspection: 679703789




Photo 1. Location looking southwest.



Photo 2. Unused sign & uncapped riser.

Inspection Photos

Location Name: GRAY B 19X

Location ID: 05-103-66397

Inspection: 679703789



Photo 3. Breached stormwater edge berm on northwest edge of location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources