

Inspection Photos

Location Name: GRAY B-2

Location ID: 05-103-05787

Inspection: 679703803



Photo 1. Location looking northeast.



Photo 2. Stormwater berm breach on east edge of location.

