

Inspection Photos
API#045-18851
Operator: Laramie
Insp#692400913
Inspection Date: 4/16/2019





Photo#1:
Overview of Location from entry to Southeast.

April 16, 2019



Photo#2:

Riser/Line at site of PA Well's Separator remains in place and needs to be removed

April 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie PA Knox API#045-18851