

Construction and Storm Water Inspection

April 15, 2019

Operator: NGL WATER SOLUTIONS DJ LLC - 10373

Location ID: 456888

Inspection Document #: 674902792

Weld County, CO

SWNE Section 30 T1N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 1. Photo taken from the entrance to the access road Off CR 27, facing Northeast. Photo illustrates a concrete pad installed by the Operator to potentially limit tracking on to the county road.



Photo 2. Photo taken from the access road facing Southwest. Photo depicts the storage area being utilized south of the access road.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 3. Photo taken from the northeastern perimeter of the location, facing South. Photo illustrates the installed silt fence BMP is not in proper functioning condition.



Photo 4. Photo taken from the northwestern perimeter of the location, facing East. Photo illustrates a sediment trap installed however no stabilized outlet is apparent.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 5. Photo taken from the northeastern perimeter of the location, facing North. See comments from Photo 3.



Photo 6. Photo taken from the northwestern perimeter of the location, facing East. Photo depicts the silt fence BMP that has been installed.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 7. Photo taken from the Northwestern perimeter of the location, facing North. See comments under Photo 4.



Photo 8. Photo taken from the Northwestern perimeter of the location, facing North. See comments under Photo 4.