

Inspection Photos

Loc#440634


Operator: Ursa

Inspection Number: 692400907

Inspection Date: 4/16/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to South.

April 16, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa B&V Pad Loc#440634



Photo#2:
View over Well line up; no wildlife escape boards installed.

April 16, ,2019



Photo#3:
Three Cellars filled with water; no wildlife escape boards installed.



Photo#4:
Sediment trap & drain at South corner of Location
needs maintenance.

April 16, ,2019



Photo#5:
Sediment trap & drain at South corner of Location
needs maintenance.



Photo#6:

Areas on outside of & along wire & wooden fences that are bare ground & do not appear to have been seeded; only emerged Kochia seedlings were noted

April 16, ,2019



Photo#7:

Areas on outside of & along wire & wooden fences that are bare ground & do not appear to have been seeded; only emerged Kochia seedlings were noted



Photo#8:
BMPs on access road need maintenance.

April 16, ,2019



Photo#9:
BMPs on access road need maintenance.





Photo#10:
What was parking, staging area during Construction phase.

April 16, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa B&V Pad Loc#440634