

Inspection Photos
Location Name: McCallum 133
API: 05-057-06410



Photo 1. Overview of location taken at entrance facing south.