

Interim Reclamation and Stormwater Inspection

April 23, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 435830

Inspection Document #: 674902804

Weld County, CO

NESW Section 9 T2N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KERR MCGEE OIL & GAS /2N66W9

Location ID: 435830



Photo 1. Photo taken from the access road looking into the location, facing West. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations at the location.



Photo 2. Photo taken from the location. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS /2N66W9

Location ID: 435830



Photo 3. Photo taken from the location, facing West. See comments from Photo 1.



Photo 4. Photo taken from the location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS /2N66W9

Location ID: 435830



Photo 5. Photo taken from the location, facing East. See comments from Photo 1.



Photo 6. Photo taken from the location, facing East. See comments from Photo 1.