

Inspection Photos

4/24/2019

Operator: BENCHMARK ENERGY LLC - 10380

Location ID: 312208

Inspection Doc. Number: 682504803

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: BENCHMARK ENERGY LLC - 10380
Location ID: 312208



Photo 1: Photo taken from the north end of the location, facing south. Photo shows undesirable weedy plant species such as kochia and salsola sp. have established on areas adjacent to well head.



Photo 2: Photo taken from the southeast end of the location, facing northwest. Photo shows bare areas adjacent to the well where undesirable weedy plant germination such as kochia and salsola sp. is evident