

Inspection Photos

Location Name: WEAVER RIDGE 13-9

Location ID: 05-103-10580

Inspection: 679703844



Photo 1. Location looking north.



Photo 2. Partially melted lead batteries next to compressor.

Inspection Photos

Location Name: WEAVER RIDGE 13-9

Location ID: 05-103-10580

Inspection: 679703844

Gas leak



Photo 3. Gas leak on top of separator.



Photo 4. Open pales of fluid.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: WEAVER RIDGE 13-9

Location ID: 05-103-10580

Inspection: 679703844



Photo 5. Oily soil near pump jack motor.



Photo 6. Open container with over flowing fluid and oily stained soil next to separator.

