

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2019

Submitted Date:

04/18/2019

Document Number:

696100796**FIELD INSPECTION FORM**Loc ID 416463 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416693	WELL	TA	05/18/2018	OW	123-31453	70 RANCH USX BB 35-08	TA

**General Comment:**

This is a WELL &amp; BATTERY Inspection.

Well: TA

Battery: Abandoned &amp; ALL equipment removed except for Gas meter run &amp; riser.

Abandoned Battery SE corner GPS coordinates: 40.359019, -104.397735

Reclamation progressing.

Abandoned Centralized Battery formerly served 3 Location IDs (416463, 415988, 415367). (1-well:TA, 1-well: TA, 1-well: PA).

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (fittings & pipe) at wellsite. See photo #1 Refer to Rule 603.f for guidance. (30 Days). Remove unused equipment at wellsite.		
Corrective Action:	Remove unused equipment at wellsite. Comply w/ Rule 603.f.		Date: 05/20/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter run & riser at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. See photo #2.		
Corrective Action:	Remove unused gas meter run & riser at Abandoned Battery site. Comply w/ Rule 603.f.		Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Other	# 1		corrective date
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead: w/ master & casing valves.		
Corrective Action:			Date:



Inspected Facilities									
Facility ID:	416693	Type:	WELL	API Number:	123-31453	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>TA. Battery has been abandoned. Form 4 #401935650 indicates TA status: 05/18/2018. (Approval Pending). Form 21 #401678573 indicates Approved MIT: 06/16/2018.</div>							
Corrective Action:							Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On THU APR 18, 2019 at approximately 13:01 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: 70 RANCH USX BB /35-08  Location ID: 416463  Location County: Weld County, Colorado</p> <p>While there, I observed: 1-Well(s) TA &amp; Abandoned Battery .  Routine Inspection.</p> <p>2 - Corrective Actions observed.  1.) Unused gas meter run &amp; riser at Abandoned Battery site.  Refer to Rule 603.f for guidance when machinery required to remove equipment. See photo #2.  Remove unused gas meter run &amp; riser at Abandoned Battery site. Comply w/ Rule 603.f.  2.) Unused equipment (fittings &amp; pipe) at wellsite. See photo #1  Refer to Rule 603.f for guidance. (30 Days).  Remove unused equipment at wellsite. Comply w/ Rule 603.f.  Corrective Action date: 05/20/2019.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/18/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402014883	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800509</a>
696100797	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800506">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800506</a>