

Interim Reclamation and Stormwater Inspection

April 2, 2019

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 440396

Inspection Document #: 697500030

Weld County, CO

SENE Section 35 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Hergert /35-D Pad
Location ID: 440396



Photo 1. Photo taken from the western well location, facing North. Operator has performed Interim Reclamation activities to reduce all disturbance areas only needed for production operations.

Inspection Photos
Location Name: Hergert /35-D Pad
Location ID: 440396



Photo 2. Photo taken from the southwestern well location, facing East. A graveled berm BMP has been installed around the perimeter of the location.

Inspection Photos
Location Name: Hergert /35-D Pad
Location ID: 440396



Photo 3. Photo taken from the southeastern well location, facing North. See comments under Photo 1.