

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001. Orange decommission tag for SI/TA status has been installed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:	TA		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 244188 Type: WELL API Number: 123-11981 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>On 04/23/2019, I Erica Petrie performed an inspection of the State 8-36 Wellhead (Location ID 322744), owned and operated by Noble Energy INC. Weather Conditions: Clear skies, sunny, warm. While on inspection, I observed the following issue(s) Wellhead State 8-36 has now the Orange Decommission Tag installed per Variance Alternative Mechanical Integrity Assurance Program. Doc #02385001 Continuing Education Inspection. END.</p>	petrie	04/23/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300138	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806520