



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Apr 2, 2019 3:20:12 PM MDT
Server Receive Date:	Apr 24, 2019 7:12:03 AM MDT
Reference Number:	20190424-18104503589
Location:	Unknown Location

Information

Name	colen@horizonenvservices.com
Date	Apr 2, 2019
Well Name	DUNKEL,ELMER GAS UNIT A 2
API Number	50670900200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other

Picture North to South



Picture South to North



Picture East to West



Additional photos



Additional photos



Additional photos



Completed work description

Completed a kochia treatment to reduce population size on pad.

Notes

Was not able to identify any Russian Knapweed on location, including any skeletons. Additional monitoring for Russian Knapweed is recommended.