

Construction and Storm Water Inspection

April 25, 2019

Operator: NOBLE ENERGY INC – 100322

Location ID: 458975

Inspection Document #: 674902817

Weld County, CO

SWSE Section 23 T3N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W23

Location ID: 458975



Photo 1. Photo taken from the access road looking towards the location, facing South. Appears the Operator has started construction at the location at the time of the inspection.



Photo 2. Photo taken from the access road, facing Northeast. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W23

Location ID: 458975



Photo 3. Photo taken from the northern perimeter of the location, facing East. Appears the Operator has installed filtrex BMPs around the perimeter of the location.



Photo 4. Photo taken from the northern perimeter of the location, facing West. See comments from Photo 3.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W23

Location ID: 458975



Photo 5. Photo taken from the southeastern perimeter of the location, facing West. See comments from Photo 3.



Photo 6. Photo taken from the southeastern perimeter of the location, facing North. See comments from Photo 3.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W23

Location ID: 458975



Photo 7. Photo taken from the southwestern perimeter of the location, facing North. See comments from Photo 3.



Photo 8. Photo taken from the southwestern perimeter of the location, facing East. See comments from Photo 3.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W23

Location ID: 458975



Photo 9. Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 3.



Photo 10. Photo taken from the northwestern perimeter of the location, facing South. See comments from Photo 3.