

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



KNIGHT W-13-3

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



Well heads

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



Open rathole at well.

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



Open rathole at well. Shovel laying over rathole.



Shovel handle in rathole.

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



Open rathole at well.



Shovel handle in rathole.

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



Open rathole at well.



Shovel handle in rathole.

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



Open rathole at well.



Shovel handle in rathole.

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



Open rathole at well.



Shovel handle in rathole.

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



Separators and tank battery.



300 bbl tank removed from tank berm.

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



Unused tank on side of access road within roughly 250 ft. of the Colorado river.



300 bbl Production tank has been removed from tank battery and has been stored on shoulder of access road.

GV 52-3
Api. # 05-045-06652
Inspection # 689703084



**Unsued 2" pipe laying off side of road between well pad and
production tank and separator battery**