

# Inspection Photos

API: 05-071-06399

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/25/2019

## Inspection Photos



**Photo 1.** Facing southeast along the reclaimed access road.



## Inspection Photos



**Photo 2.** Facing southeast along the reclaimed access road.



## Inspection Photos



**Photo 3.** Facing southeast along the reclaimed access road. Vegetation is establishing along the reclamation area.



## Inspection Photos



**Photo 4.** Facing south toward the recontoured and reclaimed location.



## Inspection Photos



**Photo 5.** Facing northwest toward the location from across the canyon.