

## Inspection Photos

Location Name: CARLSON-66N61W /22E2NW

Location #: 327707



**Photo #1**

**Carlson 22-1 (05-123-15054) Wellsite**

**Weeds**

*from prior FIR*



**Photo #2**

**Carlson 22-1 Wellsite**

**Weeds – appear NOT addressed**



**Inspection Photos**  
**Location Name: CARLSON-66N61W /22E2NW**  
**Location #: 327707**



**Photo #3**  
**Carlson 22-1 Battery**  
*from prior FIR*



**Photo #4**  
**Carlson 22-1 Battery**

## Inspection Photos

Location Name: CARLSON-66N61W /22E2NW

Location #: 327707



**Photo #5**

**Carlson 22-1 Oil tanks**

**Weeds around back & front of oil tanks**

*from prior FIR*



**Photo #6**

**Carlson 22-1 Oil tanks**

**Weeds around oil tanks**

***Some weeds remain***



**Inspection Photos**  
**Location Name: CARLSON-66N61W /22E2NW**  
**Location #: 327707**



**Photo #7**  
**Carlson 22-1 Treater**  
**Weeds around treater & treater house**  
*from prior FIR*



**Photo #8**  
**Carlson 22-1 Treater**  
**Weeds around treater & treater house**  
***Some weeds remain***

## Inspection Photos

Location Name: CARLSON-66N61W /22E2NW

Location #: 327707



**Photo #9**

**Carlson 22-1 Wellsite**

**Unused equipment at wellhead  
(Pumping unit, gas engine)**

**Weeds on site**

*from prior FIR*



**Photo #10**

**Carlson 22-1 Wellsite**

**Unused equipment at wellhead  
(Pumping unit, gas engine)**

**Remains on site**

**Weeds remain on site**



## Inspection Photos

Location Name: CARLSON-66N61W /22E2NW

Location #: 327707



**Photo #11**

**Carlson 22-1 H2O tank & pit**

**Weeds**

*from prior FIR*



**Photo #12**

**Carlson 22-1 H2O tank & pit**

**Weeds**

***Some weeds remain***

