

Final Reclamation Inspection

April 24, 2019

Operator: DJ RESOURCES INC- #10213

API: 05-069-06435

Inspection Document #: 697500050

Larimer County, CO

NWSE Section 16 T10N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rawhide Flats 10-68-16
API: 05-069-06435



Photo 1. Photo taken from the entrance of the location off CR7, facing West. Operator has failed to remove all gravel from the access road, as there was little to no germination of desirable species. Operator failed to properly contour the access road per Rule 1004.

Inspection Photos
Location Name: Rawhide Flats 10-68-16
API: 05-069-06435



Photo 2. Photo taken along a portion of the access road, facing West. Operator has failed to remove all debris (t-posts) from along the access road.



Photo 3. Photo taken along a portion of the access road, facing West. See comments under Photo 2.

Inspection Photos
Location Name: Rawhide Flats 10-68-16
API: 05-069-06435



Photo 4. Photo taken just east of the Freshwater Emergent Wetland, facing East. Operator has failed to properly contour the access road per Rule 1004.

Inspection Photos

Location Name: Rawhide Flats 10-68-16

API: 05-069-06435



Photo 5. Photo taken from the Freshwater Emergent Wetland, facing West. Operator has failed to remove all gravel from the access road. Gravel from the access road has eroded into the wetland.

Inspection Photos
Location Name: Rawhide Flats 10-68-16
API: 05-069-06435



Photo 6. Photo taken on the east-side of the wetland. Operator has failed to remove debris used to cross the wetland during operations.



Photo 7. Photo taken from the wetland, facing South. See comments under Photo 2.

Inspection Photos
Location Name: Rawhide Flats 10-68-16
API: 05-069-06435



Photo 8. Photo taken near the wetland. See comments under Photo 2.



Photo 9. Photo taken from the wetland, facing South. See comments under Photo 2.

Inspection Photos
Location Name: Rawhide Flats 10-68-16
API: 05-069-06435



Photo 10. Photo taken along the western access road, facing West. See comments under Photo 1.

Inspection Photos
Location Name: Rawhide Flats 10-68-16
API: 05-069-06435



Photo 11. Photo taken from the northeastern location on 7/16/2018, facing South. Little, to no, germination of desirable species was observed throughout most of the location. Kochia, the green foliage illustrated in the photo, was observed throughout most of the location. Operator shall control and manage the weedy, annual Kochia until location meet Rule 1004 vegetation standards.

Inspection Photos
Location Name: Rawhide Flats 10-68-16
API: 05-069-06435



Photo 12. Photo taken from the northeastern location on 4/24/2019, facing South. There is little, to no, germination of desirable species was observed throughout most of the location.

Inspection Photos
Location Name: Rawhide Flats 10-68-16
API: 05-069-06435



Photo 13. Photo taken from the central location on 4/24/2019, facing South. See comments under Photo 12.

Inspection Photos
Location Name: Rawhide Flats 10-68-16
API: 05-069-06435



Photo 14. Photo taken from the western location on 4/24/2019, facing Northwest.
See comments under Photo 12.

Inspection Photos

Location Name: Rawhide Flats 10-68-16

API: 05-069-06435



Aerial imagery taken from the National Wetlands website illustrates the Freshwater Emergent Wetland.