

## Inspection Photos

Location Name: BASTER PASS 43-21

Location ID: 05-103-09851

Inspection: 679703878



Photo 1. Location looking north.



Photo 2. Missing "911" on sign. (Nearest Public Rd barely legible).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: BASTER PASS 43-21

Location ID: 05-103-09851

Inspection: 679703878

Capacity was here



Photo 3. Uncapped riser between meter building and pit.




Photo 4. Tank capacity not legible.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: BASTER PASS 43-21

Location ID: 05-103-09851

Inspection: 679703878



**Photo 5. No well head sign.**



**Photo 6. Dead weeds on berm.**

