

Inspection Photos

API#103-06281

Operator: Rio Mesa Resources

Inspection #: 692400856

Inspection Date 3/28/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to South.

March, 28, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Rio Mesa PA API#103-40021



Photo#2:
View of stained soil to East.

March, 28, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Rio Mesa PA API#103-40021



Photo#3:

A few pieces of small diameter cable debris were noted.

March, 28, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Rio Mesa PA API#103-40021



Photo#4:
View North over Marker.

March, 28, 2019



Photo#5:
Should check for subsidence at base of Marker.