

Inspection Photos

4/26/2019

Operator: BISON OIL & GAS II LLC # 10661

Location ID: 452871

Inspection Doc. Number: 682504817

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the east end of the location facing south. Photo shows operator has installed a ditch along the eastern perimeter of the pad.



Photo 2: Photo taken from the southeast end of the location, facing southeast. Photo shows operator has installed a ditch. Photo also shows erosion degradation has been repaired and slopes appear to have been seeded/mulched.



Photo 3: Photo taken from the southwest end of the pad, facing north. Photo shows operator has installed a stormwater ditch on the western perimeter of the pad.



Photo 4: Photo taken from the southwest end of the pad, facing east. Photo shows operator has installed a stormwater ditch on the western perimeter of the pad. Photo shows operator appears to have conducted weed management on berm.



Photo 5 See comments under photo 4.



Photo 6: Photo taken from the northwest end of the location, facing northwest. Photo shows velocity checks within ditch.



Photo 7: Photo taken from the northwest corner of the location, facing north. Photo shows operator has updated the sediment trap.



Photo 8: Photo taken from the northeast corner of the location, facing east. Photo shows operator has updated the sediment trap.

Inspection Photos
Operator: BISON OIL & GAS II LLC # 10661
Location ID: 452871



Photo 9: Photo taken from the east end of the location. Previous inspection documented various trash debris on the east end of the location, and required operator to remove and properly store in accordance with 603.f. Photo shows various debris remains.