

Inspection Photos

4/26/2019

Operator: VERDAD RESOURCES LLC # 10651

Location ID: 457136

Inspection Doc. Number: 682504819

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the south end of the location, facing east. Photos 1-4 provide an overview of the location from east, southeast, southwest to west. Photos show construction in process. Photo also shows operator has installed a stormwater ditch along the perimeter of the disturbance area.



Photo 2: See comments under photo 1.



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1. Stormwater ditch does not appear to have been installed in accordance with good engineering practices; ditch appears to have been cut with a vertical grade. BMP will need to be updated once pad construction has been completed.



Photo 5 Photo shows operator utilizing a water truck to mitigate fugitive dust on location and access road.



Photo 6: Photo taken from northeast corner of the location, facing south. Photo shows perimeter ditch and soil stockpile. Topsoil salvage in process at time of inspection.



Photo 7: Photo taken from northeast corner of the location, facing west. Photo shows scraper being used to salvage soil from location.

Inspection Photos
Operator: VERDAD RESOURCES LLC # 10651
Location ID: 457136




Photo 8: Photo shows a disturbance area of 6.05 acres mapped with a Trimble Juno 3B GPS unit; this appears to be in compliance with the approved Form 2A for the permitted disturbance area.