

Inspection Photos
Location Name: Damfino Pad
Location ID: 416625



Photo 1. Overview of location taken from northwest corner facing southeast.



Photo 2. Overview of location taken at entrance facing northwest.

Inspection Photos
Location Name: Damfino Pad
Location ID: 416625



Photo 3. Stained soil at wellhead.