

Inspection Photos
Location Name: REU 0681 1-23H2
API: 05-057-06598



Photo 1. Overview of location taken from southwest corner facing northeast.



Photo 2. Load out hose without containment.