

Inspection Photos
Spill/Release Name: HSC-5 Pipeline
Spill/Release ID: #461292
Inspection Date: April 23, 2019



Photo #1 – Overview of backfilled excavation area from southeast. Note that backfilled excavation has been covered with gravel/road base and not re-seeded.



Photo #2 – Trash and junk remains north of backfilled excavation area.