

Inspection Photos
Operator: BP America
Location/API #: 067-08818
Date: 4-17-2019



Photo 1. View of the southern project area from the southeastern edge facing westward.



Photo 2. View of the eastern project area from the southeastern edge facing northward.



Photo 3. View of rilling and erosion along the southeastern edge of the working area.