

# Inspection Photos

Operator: Catamount Energy  
Location/API #: 067-09609  
Date: 4-17-2019



Photo 1. View of the southern project area from the southeastern edge facing westward.





Photo 2. View Russian thistle debris and other waste within the eastern project area.





Photo 3. View of the northern project area from the northeastern corner facing westward.