

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 1 - Wellheads



Photo 2 – Tank Battery

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 3 – Well Detterer FD 25-6D, API 123-35571, missing wellhead signage.



Photo 4 – Well Detterer FD 24-21D, API 123-35575, missing wellhead signage.

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



**Photo 5 – Unknown Non E&P waste in open top container,
on the northwest on location by the ECDs**



Photo 6 – Stained soil on northwest of location

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 7 – Stained soil at the drain plug on the northeast Crude Oil tank.



Photo 8 – Stained soil on south ECD knock-out pot, north side of Crude Oil tanks.