

Inspection Photos
Location Name: Shannon-Roberts #3
Location ID: 321500



Photo 1 TNK BTRY

Photo 2 WH. Well is SI.

Inspection Photos
Location Name: Shannon-Roberts #3
Location ID: 321500



**Photo 3 Stained soil under crude oil load out line.
Mechanical issue Valve or bull plug appears to be leaking.**

Photo 4 Trash: furniture, dead weeds on location.

Inspection Photos
Location Name: Shannon-Roberts #3
Location ID: 321500



Photo 5 Loc pic

Photo 6 Crude oil tank gravel appears to be eroding away form underneath base of tank.