

Inspection Photos
Location Name: Shannon-Roberts #1A
Location ID: 321499



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Shannon-Roberts #1A
Location ID: 321499



Photo 3 Mechanical issue: inside separator house appears piping to separator is leaking.



Photo 4 stained soil under what appears to be leaking piping to separator.

Inspection Photos
Location Name: Shannon-Roberts #1A
Location ID: 321499



Photo 5 Debris/weeds: Dead weeds on location.



Photo 6 Unused, unmarked not LOTO or bull plugged riser.

Inspection Photos
Location Name: Shannon-Roberts #1A
Location ID: 321499



Photo 7 TNK BTRY



Photo 8 inadequate berm around crude oil tank. Burrows in containment walls.

Inspection Photos
Location Name: Shannon-Roberts #1A
Location ID: 321499



Photo 9 Trash/Weeds. Dead weeds on location.