

GM 41-11
Api. # 05-045-07624
Inspection # 689703100



GM 41-11
Api. # 05-045-07624
Inspection # 689703100



Channeling through berm

GM 41-11
Api. # 05-045-07624
Inspection # 689703100



Sediment build up behind the location berm.

GM 41-11
Api. # 05-045-07624
Inspection # 689703100



Channeling through berm



Riling at the outlet of channel.

GM 41-11
Api. # 05-045-07624
Inspection # 689703100



Sediment build on waddles.