

Laramie Energy LLC
Api # 05-077-08428
Inspection # 696600006



Photo at entrance to location.

Laramie Energy LLC
Api # 05-077-08428
Inspection # 696600006



Photo of tank battery



Photo of wellhead.

Laramie Energy LLC
Api # 05-077-08428
Inspection # 696600006



Dirt berm does not allow 2 feet of free board.



Dirt Berm for secondary containment is in need of maintenance.