

**Laramie Energy LLC**  
**Api # 05-077-08426**  
**Inspection # 696600014**



**Photo at entrance to location.**

Laramie Energy LLC  
Api # 05-077-08426  
Inspection # 696600014



Tank Battery



Wellhead.



**Laramie Energy LLC**  
**Api # 05-077-08426**  
**Inspection # 696600014**



**Trash or unused equipment on location.**



**Trash or unused equipment on location.**



**Laramie Energy LLC**  
**Api # 05-077-08426**  
**Inspection # 696600014**



**Unmarked stakes sticking out of the ground**



**Trash piled up on corner of location by Deadman marker.**



**Laramie Energy LLC**  
**Api # 05-077-08426**  
**Inspection # 696600014**



**Erosion evident. No BMP to catch sediment**



**Erosion evident. No BMP to catch sediment**



**Laramie Energy LLC**  
**Api # 05-077-08426**  
**Inspection # 696600014**



**Erosion has made a channel moving soil off location.**



**Erosion has made a channel moving soil off location. (Close up photo)**



**Laramie Energy LLC**  
**Api # 05-077-08426**  
**Inspection # 696600014**



**Hole through Berm . BMP needs Maintenance.**



**Hole through Berm . BMP needs Maintenance.**



**Laramie Energy LLC**  
**Api # 05-077-08426**  
**Inspection # 696600014**



**Hole through Berm . BMP needs Maintenance.**



**Trash on location.**



Laramie Energy LLC  
Api # 05-077-08426  
Inspection # 696600014



**BMP full of sediment. needs maintenance.**



**BMP full of sediment. needs maintenance.**



**Laramie Energy LLC**  
**Api # 05-077-08426**  
**Inspection # 696600014**



**Erosion moving sediment off location, Vegetation not present**



**BMP full of sediment. needs maintenance.**



**Laramie Energy LLC**  
**Api # 05-077-08426**  
**Inspection # 696600014**



**Secondary Berm or containment needs maintenance**



**Secondary Berm or containment needs maintenance**