

Inspection Photos
Location Name: Joseph J.C Pain #NO 1 Anadarko
Location ID:414601



Photo 1 Loc Pic. Debris/ weeds: dead weeds on location.



Photo 2 Stained soil around WH.

Inspection Photos
Location Name: Joseph J.C Pain #NO 1 Anadarko
Location ID:414601



Photo 3 Stained soil around WH.



Photo 4 Stained soil around WH.

Inspection Photos
Location Name: Joseph J.C Pain #NO 1 Anadarko
Location ID:414601



Photo 5 WH sign does not have emergency contact number



Photo 6 Unused equipment: propane tank and sucker rods.

Inspection Photos
Location Name: Joseph J.C Pain #NO 1 Anadarko
Location ID:414601



Photo 7 Stained soil around PU motor. Trash: 5 gallon bucket.



Photo 8 Loc Pic Debris/weeds: dead weeds on location.

Inspection Photos
Location Name: Joseph J.C Pain #NO 1 Anadarko
Location ID:414601



Photo 9 Stained soil around PU motor. Trash: 5 gallon bucket.



Photo 10 Loc Pic Debris/weeds: dead weeds around PU.

Inspection Photos

Location Name: Joseph J.C Pain #NO 1 Anadarko

Location ID:414601



Photo 11 Trash inside PU base.



Photo 12 Loc Pic Debris/weeds: dead weeds around location.

Inspection Photos
Location Name: Joseph J.C Pain #NO 1 Anadarko
Location ID:414601



Photo 13 Loc Pic Debris/weeds: dead weeds around location.



Photo 14 Loc Pic Debris/weeds: dead weeds around location.

Inspection Photos
Location Name: Joseph J.C Pain #NO 1 Anadarko
Location ID:414601



Photo 15 TNK BTRY sign has a non-working emergency contact number.



Photo 16 TNK BTRY

Inspection Photos
Location Name: Joseph J.C Pain #NO 1 Anadarko
Location ID:414601



Photo 17 Labels and placards not litigable or not on crude oil tanks.



Photo 18 Labels and placards not litigable or not on crude oil tanks. Visual impact: tank visible from county road paint in disrepair.

Inspection Photos
Location Name: Joseph J.C Pain #NO 1 Anadarko
Location ID:414601



Photo 19 Unused equipment: Stairs in disrepair.



Photo 20 Trash: Boat, and trash scattered through out location.

Inspection Photos
Location Name: Joseph J.C Pain #NO 1 Anadarko
Location ID:414601



Photo 21 Trash and Debris/weeds on edge of location



Photo 22 Trash and Debris/weeds on edge of location.

Inspection Photos

Location Name: Joseph J.C Pain #NO 1 Anadarko

Location ID:414601



Photo 23 Sep house and EC.D



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources