

Inspection Photos  
Location Name: Linda #1  
Location ID: 319555



Pic 1



Pic 2 chemical barrel appears to be leaking. No containment.

**Inspection Photos**  
**Location Name: Linda #1**  
**Location ID: 319555**



**Pic 3. Possible leak**



**Pic 4 possible leak.**



**Inspection Photos**  
**Location Name: Linda #1**  
**Location ID: 319555**



**Pic 5**



**Pic 6 possible leak**