

**Inspection Photos**  
**Location Name: BEHRING-66N61W /35SESE**  
**Location #: 317496**



**Photo #1**  
**Behring #1 Wellsite**  
**Shut-In | SI**  
**Stained soil**  
*from prior FIR*



**Photo #2**  
**Behring #1 (05-123-05198) Wellsite**  
**Shut-In | SI**  
**Weeds, Stained soil**

**Inspection Photos**  
**Location Name: BEHRING-66N61W /35SESE**  
**Location #: 317496**



**Photo #3**  
**Behring #1 Battery**  
**Shut-down**  
**Weeds**  
*from prior FIR*



Colorado Oil & Gas Conservation Commission  
40.44042, -104.1695, 1402.0m, 280°  
04/29/2019 03:17:02 PM

**Photo #4**  
**Behring #1 Battery**  
**Shut-down**  
**Weeds**



**Inspection Photos**  
**Location Name: BEHRING-66N61W /35SESE**  
**Location #: 317496**



**Photo #5**  
**Behring #1 Treater**  
**Shut-down**  
**Weeds**  
*from prior FIR*



**Photo #6**  
**Behring #1 Treater, H2O tank**  
**Shut-down**  
**Weeds**

**Inspection Photos**  
**Location Name: BEHRING-66N61W /35SESE**  
**Location #: 317496**



**Photo #7**  
**Behring #1 Pit excavation – South side**  
**Unused Equipment - Pipe**  
*from prior FIR*



**Photo #8**  
**Behring #1 Pit excavation – South side**  
**Unused Equipment - Pipe**

**Inspection Photos**  
**Location Name: BEHRING-66N61W /35SESE**  
**Location #: 317496**



**Photo #9**  
**Behring #1** Pit excavation – East side  
**Debris, risers**  
*from prior FIR*



**Photo #10**  
**Behring #1** Pit excavation – East side  
**Debris, risers**  
**Weeds**

**Inspection Photos**  
**Location Name: BEHRING-66N61W /35SESE**  
**Location #: 317496**



**Photo #11**  
**Behring #1 Crude oil tanks - Loadout**  
**Stained soil**  
*from prior FIR*



**Photo #12**  
**Behring #1 Crude oil tanks - Loadout**  
**Stained soil**

**Inspection Photos**  
**Location Name: BEHRING-66N61W /35SESE**  
**Location #: 317496**



**Photo #13**  
**Behring #1 Crude oil tanks**  
**Rust**  
*from prior FIR*



**Photo #14**  
**Behring #1 Crude oil tanks**  
**Rust**

**Inspection Photos**  
**Location Name: BEHRING-66N61W /35SESE**  
**Location #: 317496**



**Photo #15**  
**Behring #1 Pumping Unit Eng. House**  
**Stained soil**  
*from prior FIR*



**Photo #16**  
**Behring #1 Pumping Unit Eng. House**  
**Stained soil**

**Inspection Photos**  
**Location Name: BEHRING-66N61W /35SESE**  
**Location #: 317496**



**Photo #17**  
**Behring #1 Crude Oil tanks**  
**Berms – Burrows, Weeds**  
*from prior FIR*



**Photo #18**  
**Behring #1 Crude Oil tanks**  
**Berms – Burrows, Weeds**

**Inspection Photos**  
**Location Name: BEHRING-66N61W /35SESE**  
**Location #: 317496**



**Photo #19**  
**Behring #1** Land farm  
**Facing West**  
*from prior FIR*



**Photo #20**  
**Behring #1** Land farm  
**Facing West**

