

Inspection Photos

Location Name: DOC STATE-66N61W /36NENW

Location #: 330865



Colorado Oil & Gas Conservation Commission
40.45011, -104.15657, 1392.0m, 274°
04/29/2019 02:14:40 PM

Photo #1

State 36-3-9 (API # 05-123-19794) Wellsite

Temporarily Abandoned | TA



Colorado Oil & Gas Conservation Commission
40.44994, -104.15639, 1401.0m, 10°
04/29/2019 02:38:24 PM

Photo #2

State 36-3-9, 36-6 Battery

Shut-down



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: DOC STATE-66N61W /36NENW
Location #: 330865



Photo #3
State 36-3-9 Wellsite
Stained soil
from prior FIR



Photo #4
State 36-3-9 Wellsite
Stained soil
Appears mitigated

Inspection Photos

Location Name: DOC STATE-66N61W /36NENW

Location #: 330865



Photo #5

State 36-3-9, 36-6 Battery

Battery sign illegible / missing info.

from prior FIR



Photo #6

State 36-3-9, 36-6 Battery

Battery sign Legible / Complete info.

Inspection Photos

Location Name: DOC STATE-66N61W /36NENW

Location #: 330865



Photo #7

State 36-3-9, 36-6 Location

N. Side storm water erosion

from prior FIR



Photo #8

State 36-3-9, 36-6 Location

N. Side storm water erosion

remains



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: DOC STATE-66N61W /36NENW

Location #: 330865



Photo #9

State 36-3-9, 36-6 Pit

Animal burrow NW side of pit
from prior FIR



Photo #10

State 36-3-9, 36-6 Pit

Animal burrow NW side of pit
Appears mitigated



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: DOC STATE-66N61W /36NENW

Location #: 330865



Photo #11

State 36-3-9, 36-6 Pit

Unpermitted pit
from prior FIR



Photo #12

State 36-3-9, 36-6 Pit

Animal burrow NE side of pit
Pit now permitted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: DOC STATE-66N61W /36NENW

Location #: 330865



Photo #13

State 36-3-9 Wellsite

Fencing in disrepair
from prior FIR



Photo #14

State 36-3-9 Wellsite

Fencing NOW intact



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: DOC STATE-66N61W /36NENW

Location #: 330865



Photo #15

State 36-3-9, 36-6 Pit

H2O skim tank

Capacity NOT Legible



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources