

Inspection Photos
Location Name: Duncan B 11
API: 05-081-07030



Photo 1. Overview of location taken at entrance facing north.