

Location Name: LOWELL BRADY 23-3A

Location ID: 05-103-07642

Inspection: 679703907



Photo 1. Location looking northwest.



Location Name: LOWELL BRADY 23-3A

Location ID: 05-103-07642

Inspection: 679703907

Gas leak



Photo 2. No berm on east side of tank battery.

Photo 3. Gas leak at well head. Gage was attached on 10/3/2018 where gas leak is now occurring.

