

Inspection Photos

Location Name: McClellan LG09-72HN Location ID 432140, Spill ID #463958

Inspection Date: 4/30/2019



04/30/19 11:30 AM

Photo 1 – View of dismantled tank battery with liner present.



04/30/19 11:30 AM

Photo 2 – Buried concrete produced water vessel within tank battery secondary containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources