

Inspection Photos

Location Name: Wahlert AC 33-63HN Tank Location ID 425777, Spill ID #463844

Inspection Date: 4/30/2019



Photo 1 – Potholes/investigation near buried produced water vessel within non-lined secondary containment.



Photo 2 - Potholes/investigation near buried produced water vessel within non-lined secondary containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources