

Inspection Photos

4/30/2019

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 463808

Inspection Doc. Number: 682504833

Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northwest corner of the location, facing east. Photo shows construction activities in process. Photo also shows operator has installed surface roughening along perimeter of the location.



Photo 2: Photo taken from the northwest corner of the location, facing south. Photo shows construction activities in process. Photo also shows operator has installed surface roughening along perimeter of the location. .



Photo 3: Photo taken from the soil stockpile on the south end of the location. Operator has implemented tracking to stabilize soil stockpiles.



Photo 4: Photo taken from access road entrance. Photo shows culvert installed with inlet/outlet armoring.