

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2019

Submitted Date:

05/01/2019

Document Number:

690003474**FIELD INSPECTION FORM**
 Loc ID 331619 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|-------------------------------|---------------------------------|
| , Inspections | | COGCCinspections@Anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 264028 | WELL | SI | 12/01/2018 | GW | 123-20992 | PSC 16-13A | TA |
| 422714 | WELL | PR | 01/02/2014 | OW | 123-33362 | PSC 13N-13HZ | PR |
| 422716 | WELL | PR | 01/02/2014 | OW | 123-33364 | PSC 12N-13HZ | PR |
| 422730 | WELL | PR | 02/01/2017 | OW | 123-33365 | PSC 12C-13HZ | PR |
| 422739 | WELL | PR | 01/02/2014 | OW | 123-33367 | PSC 13C-13HZ | PR |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | Date: _____ |
| Corrective Action: | | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 4 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|---------------------|---------|-----------------------|
| | | | CENTRALIZED BATTERY | | 40.219220,-104.943530 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 264028 | Type: WELL | API Number: 123-20992 | Status: SI | Insp. Status: TA |
|---------------------|------------|-----------------------|------------|------------------|

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 422714 | Type: WELL | API Number: 123-33362 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: pr

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 422716 | Type: WELL | API Number: 123-33364 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: pr

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 422730 | Type: WELL | API Number: 123-33365 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: pr

Corrective Action:

Date:

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 422739 | Type: WELL | API Number: 123-33367 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

Comment: pr

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

On Wednesday, May 1, 2019 at 11:18, I, Craig Carlile conducted an on-site inspection at: 331619 Operated by: Anadarko
 While there I observed: 4 Producing Wells, One well has been plugged and is awaiting casing cut, well covered by night cap, 05-123-20992 PSC 16-13A form 6 document number: 401552725
 Possible compliance issues observed: None: ?
 This is a summary of the inspection report.

carlilec

05/01/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 690003475 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811699 |