

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402011543

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	Phone Numbers
Address: P O BOX 173779		
City: DENVER	State: CO Zip: 80217-3779	
Contact Person: Erik Mickelson	Email: Erik.Mickelson@anadarko.com	
		Phone: (720) 929-6000
		Mobile: (720) 929-4306

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 11035

Initial Form 27 Document #: 401502037

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input checked="" type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: SPILL OR RELEASE	Facility ID: 437084	API #:	County Name: WELD
Facility Name: SPILL/RELEASE POINT		Latitude: 40.017826	Longitude: -104.870207
		** correct Lat/Long if needed: Latitude:	Longitude:
QtrQtr: SESE	Sec: 27	Twp: 1N	Range: 67W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications CL

Most Sensitive Adjacent Land Use Crop Land

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

A building is located approximately 300 feet southeast of the release location.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☐ Oil ☐ Tank Bottoms
- ☒ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	See attached data	Groundwater sampling and laboratory analysis
Yes	SOILS	55' (E-W) x 15' (N-S) x 7' bgs	Excavation, soil sampling, and laboratory analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On May 1, 2014, historical impacts were discovered during abandonment activities at the Howard 25C-22HZ production facility, and excavation activities were initiated. Groundwater was encountered in the excavation at approximately 4 feet below ground surface (bgs). The COGCC has issued Spill/Release Point ID 437084 for this release.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Soil samples were collected as described in the Initial Form 27. Based on the data presented, impacted soils in the excavation area were remediated to be in full compliance with COGCC standards. Soil sample analytical data is presented in Table 1, and the soil sample locations are illustrated on Figure 1.

Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater samples were collected as described herein. Based on the data presented, hydrocarbon impacts to groundwater were remediated to be in full compliance with COGCC standards. Groundwater analytical data is presented in Table 2. The excavation groundwater sample location is illustrated on Figure 1, and the temporary groundwater monitoring well locations are illustrated on Figures 2 through 5. The laboratory analytical reports for the previous four quarters of monitoring are provided as Attachment A.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 6
Number of soil samples exceeding 910-1 0
Was the areal and vertical extent of soil contamination delineated? Yes
Approximate areal extent (square feet) 825

NA / ND

-- Highest concentration of TPH (mg/kg) 52.2
NA Highest concentration of SAR
BTEX > 910-1 No
Vertical Extent > 910-1 (in feet) 7

Groundwater

Number of groundwater samples collected 103
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) 9'
Number of groundwater monitoring wells installed 15
Number of groundwater samples exceeding 910-1 5

-- Highest concentration of Benzene (µg/l) 311
-- Highest concentration of Toluene (µg/l) 21.3
-- Highest concentration of Ethylbenzene (µg/l) 74.4
-- Highest concentration of Xylene (µg/l) 232
NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected
0 Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Between May 1 and 7, 2014, approximately 220 cubic yards of impacted soil were excavated and transported to the Front Range Landfill in Erie, Colorado for disposal. Laboratory analytical results indicated that constituent concentrations in the soil samples collected from the final lateral extent of the excavation area were in full compliance with COGCC standards. Soils were excavated into the phreatic zone to address potential hydrocarbon impacts that may have been present below the current groundwater table due to seasonal fluctuations. Groundwater was encountered in the excavation area at approximately 4 feet bgs. A groundwater sample (GW01) was collected from the excavation and submitted for laboratory analysis of BTEX. Groundwater analytical results received on May 2, 2014, indicated that the benzene concentration in sample GW01 was out of compliance with the COGCC standard. Approximately 50 barrels of impacted groundwater were subsequently removed from the excavation area via vacuum truck and transported to a licensed disposal facility. Groundwater did not return to the excavation following vacuum removal.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Based on the analytical data presented herein, remediation is complete at this site and Kerr-McGee is requesting a No Further Action (NFA) determination for this release.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

☒ Ex Situ

Yes _____ Excavate and offsite disposal

If Yes: Estimated Volume (Cubic Yards) _____ 220

Name of Licensed Disposal Facility or COGCC Facility ID # _____

_____ Excavate and onsite remediation

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

No _____ Bioremediation (or enhanced bioremediation)

No _____ Chemical oxidation

No _____ Air sparge / Soil vapor extraction

Yes _____ Natural Attenuation

Yes _____ Other _____ Groundwater removal

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Between November 10, 2014 and April 23, 2018, a total of fifteen (15) temporary groundwater monitoring wells (BH01 - BH11, BH07R, BH07R2, BH09R, BH10R) were installed at the site to further assess the extent of groundwater impacts. Wells BH07, BH07R, BH09, and BH10 were consistently dry and were subsequently replaced. The temporary monitoring wells were sampled on a quarterly basis and submitted for laboratory analysis of BTEX. Analytical results for the groundwater samples collected from the temporary monitoring wells indicated that constituent concentrations were in full compliance with COGCC standards for four consecutive quarters. Temporary groundwater monitoring well locations and quarterly groundwater elevation contour maps are illustrated on Figures 2 through 5. Well completion logs for the temporary monitoring wells are provided as Attachment B.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☒ Other Final Report

Report Type: ☒ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☒ Other NFA Request

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

NA

Volume of E&P Waste (solid) in cubic yards 220

E&P waste (solid) description Hydrocarbon impacted soil

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: Front Range Landfill - Erie, Colorado

Volume of E&P Waste (liquid) in barrels 50

E&P waste (liquid) description Hydrocarbon impacted groundwater

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: Licensed disposal facility

REMEDATION COMPLETION REPORT

REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

Do all soils meet Table 910-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? No

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? Yes

Is additional groundwater monitoring to be conducted? No

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The site has been restored to its pre-release grade. Kerr-McGee will consult with the surface owner to determine reclamation specifics to properly conduct reclamation activities in accordance with COGCC 1000 Series Rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). _____ 05/01/2014

Date of commencement of Site Investigation. _____ 05/01/2014

Date of completion of Site Investigation. _____ 04/23/2018

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____ 05/01/2014

Date of completion of Remediation. _____ 03/14/2019

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

As described, laboratory analytical data for the soil samples collected from the final lateral extent of the excavation were in full compliance with COGCC standards. Laboratory analytical data for the groundwater samples collected from the temporary monitoring wells indicated that constituent concentrations were in full compliance with COGCC standards for four consecutive quarters. Soil analytical results are summarized in Table 1, and groundwater analytical results are summarized in Table 2. Excavation soil and groundwater sample locations are illustrated on Figure 1; temporary monitoring well locations and quarterly groundwater contour maps are illustrated on Figures 2 through 5. Laboratory analytical reports and temporary monitoring well completion diagrams are provided as Attachments A and B, respectively. Based on the remediation activities completed at the site and the analytical results presented herein, Kerr-McGee is requesting an NFA determination for this release.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Erik Mickelson

Title: Staff Env Representative

Submit Date: _____

Email: Erik.Mickelson@anadarko.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: 11035

COA Type**Description**

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402011938	LOGS
402011942	SOIL SAMPLE LOCATION MAP
402011944	GROUND WATER ELEVATION MAP
402011983	ANALYTICAL RESULTS
402012005	ANALYTICAL RESULTS
402012009	ANALYTICAL RESULTS

Total Attach: 6 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)