

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2019

Submitted Date:

05/03/2019

Document Number:

697600068

FIELD INSPECTION FORMLoc ID 332752 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446293	TANK BATTERY	AC	06/22/2016		-	FIVE RIVERS K 09-28D TANK	EI

General Comment:

separate inspection of production facilities
labeled as serving Five Rivers USX K9-2D, Five Rivers USX K 9-18D, Five Rivers USX K 9-7D, Five Rivers USX K 9-21D, Five Rivers
USX K 9-24D,

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: adequate

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: no spills seen at surface

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	anchored earthen berm		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	300 BBLs	STEEL AST		,	
Comment: tanks anchored with cable over top of all crude tanks						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	<100 BBLs	CONCRETE SUMP/VAULT		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment: same berm system as crude tanks				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	446293	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	EI

--