

Inspection Photos

Location Name: BASHOR PC AA /09-08

Location #: 420596



Photo #1

Bashor PC AA 9-08 (05-123-32642) Wellsite

Shut-In| SI



Photo #2

Bashor PC AA 9-08, 9-22, 9-23 Battery

Shut-down

Inspection Photos
Location Name: BASHOR PC AA /09-08
Location #: 420596



Photo #3
Bashor PC AA 9-08 Wellsite
Weeds
from prior FIR



Photo #4
Bashor PC AA 9-08 Wellsite
Weeds
Appear mitigated

Inspection Photos
Location Name: BASHOR PC AA /09-08
Location #: 420596



Photo #5
Bashor PC AA 9-08, 9-22, 9-23 Oil tank loadout
Stained soil
from prior FIR



Photo #6
Bashor PC AA 9-08, 9-22, 9-23 Oil tank loadout
Stained soil
Appears mitigated