

Inspection Photos

Location Name: BASHOR PC AA /09-22

Location #: 420599



Photo #1

Bashor PC AA 9-22 (05-123-32643) Wellsite

Shut-In| SI



Photo #2

Bashor PC AA 9-08, 9-22, 9-23 Battery

Shut-down



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: BASHOR PC AA /09-22
Location #: 420599



Photo #3
Bashor PC AA 9-22 Wellsite
Weeds
from prior FIR



Photo #4
Bashor PC AA 9-22 Wellsite
Weeds
Appear mitigated