

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2019

Submitted Date:

05/04/2019

Document Number:

696100844**FIELD INSPECTION FORM**

Loc ID 420598 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420601	WELL	SI	11/01/2018	OW	123-32644	BASHOR PC AA 09-23	SI

General Comment:[This is a WELL inspection.](#)[Well: SI](#)[Entire battery & equipment is shut-down.](#)[Centralized Battery serves 3 Location IDs \(420596, 420598, 420599\). \(1-well per location\).](#)[Refer to FIR #696100840 and/or Location ID #420596 for Battery / Facility, Equipment info.](#)

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Refer to FIR #696100840 and/or Location ID #420596 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to FIR #696100840 and/or Location ID #420596 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

		CENTRALIZED BATTERY		40.504389,-104.432704	
Comment:	Centralized Battery serves 3 Location IDs (420596, 420598, 420599). Refer to FIR #696100840 and/or Location ID #420596 for Battery / Facility, Equipment info.				
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	420601	Type:	WELL	API Number:	123-32644	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS			
Comment:		<div>SI. Observed production valves shut. COGCC records indicate last prod: 10/2018.</div>							
Corrective Action:		<div></div>					Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary: On WED 05/01/2019 at approximately 13:19 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC. Location Name: BASHOR PC AA /09-23 Location ID: 420598 Location County: Weld County, Colorado While there, I observed: Well(s) - 1: SI. Entire battery & equipment is shut-down. Centralized Battery serves 3 Location IDs (420596, 420598, 420599). Refer to FIR #696100840 and/or Location ID #420596 for Battery / Facility, Equipment info. Routine Inspection.</p> <p>No: Corrective Actions observed. This is a summary of the inspection report.</p>	evinsb	05/04/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100845	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4815236