

*Inspection Photos*  
*API#103-40302*  
*Operator: Chatham*  
*Inspection #: 692400858*  
*Inspection Date 3/29/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Area where GPS is indicating Well position.

March, 29, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chatham MV Smith #21 API#103-40302



Photo#2:

Looking to Northwest over two unknown Markers found adjacent to MV Smith#17, API#103-40303.

March, 29, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chatham MV Smith #21 API#103-40302